



Motor Start & Distribution Fuse Sizes relating to Hubbell Fuse Switches

Hubbell Fuse Switches	Maximum GEC Fuse	Maximum Bussmann Fuse	MEM Fuse	Lawson Fuse
UF32A1	NET32 NET32M63	NITD32 NITD32M63	32SA2 32SA2M63	NIT32 NIT20M32
UFS32	TIS50 TIA32M63	AA032 AA032M63	32SB3 50SB4 32SB3M63	TIA32 TIA32M63
UFS63	OS100 TIS63M100	OSD100 BAO63M100	100S0 63SB4 M100	TIS100 TIS63M100
UFS100A3	OS100 OS100M160	OSD100 OSD100M160	100S0 63SB4M100	TIS100 TIS100M125
UFS160 UFS160AC22	TFP200	DEO200 DEO200M250	125SD5 100SD5M160	TFP200 TFP200M250
UFS200	TF200 TF200M315	ED250 DD200M315	200SF6M250 250SF6	TF200 TF200M315
UFS315	TKF315 TKF315M355	ED355 ED315M400	315SF7 355SF8	TKF315 TKF315M400
UFS400	TMF400 TMF400M500	ED400 ED400M500	400SF8	TMF400 TMF400M500
UFS630	TLM800 TTM630M670	GF800	800SH10	TLM800
UFS800C3 UFS800	TLM800	GF800	800SH10	TLM800

Ordering Guide BS88 Fuses and Solid Links

	FUSES				Set of Three Solid Links
	NET25	NET32	NET32M50	NET32M63	
UFS32A1	NET25	NET32	NET32M50	NET32M63	61968-1
UFS32	NET25	NET32	NET32M50	NET32M63	62078-1
UFS63	-	-	-	-	62249-1
UFS100A3	OS100M160	-	-	-	60510-1
UFS160 UFS160AC22	-	-	-	-	62087-1
UFS200 UFS315 UFS400	-	-	-	-	60512-1
UFS630 UFS800C3	-	-	-	-	62359-1
UFS800	-	-	-	-	62263-1